						L	9 T 1	. 0 0	7,	२।		
ENGINEERING CHANGE PROPOSAL (ECP), PAGE 1					GE1		1. DATE (YYMMDI 0105	D) Form		ed)4-0188	
sources, gothering and main of this collection of informatio Operations and Reports, 121 Project (0704-0188), Washin	taining the data neede on, including suggestio 15 Jefferson Davis Higi aton, DC 20503	silon is eximated to average 2 hours p d, and completing and reviewing the in nes for reducing this burden, to Departn hway, Suite 1204, Artington, VA 22202- FORM TO EITHER OF THESE ADDRE	formation tent of De 4302, and	. Send co fense, Wi d to the O	mments regarding this ishington Headquarier flice of Management a	burden e s Service nd Budge	clions, searching slimate or any o s, Orectorate for it, Paperwork Re	existing dat ther aspect r Information duction	2. PACT	ROCURII IVITY NO .9T100	VG).	
CONTRACTING OFFICER F	OR THE CONTRACT	PROCURING ACTIVITY NUMBER L	ISTED IN	ITEM 2	F THIS FORM.	O THE G	OVERNMENT	SSUING	3. D	DDAAC		
4, ORIGINATOR a. TYPEO NAME (First, Midd	b. ADDRESS (Street, City, A.	o. ADDRESS (Street, City, State, Zip Code) U.S. ARMY ARDEC				5, CLASS OF ECP I						
BENET LABOR AMSTA-AR-CC						6. JUST. CODE 7. PRIORITY D R						
8. ORIGINATOR							SELINE AFF	ECTED				
a. MODEL/TYPE	b. CAGE CODE 19200		c. SYSTEM DESIGNATION TANK,COMBAT			FUNCTIONAL X PRODUCT ALLOCATED						
d. ECP NO.	L9T1007	R1	e. TYPE f. REV F			10. OTHER SYS./CONFIG. ITEMS AFFECTED YES X NO						
11. SPECIFICATIONS	AFFECTED				12. DRAWINGS							
	CAGE CODE	Specification/Document No.	REV.	SCN	CAGE CODE		NUM	BER		REV.	NOR	
a. SYSTEM												
b. DEVELOPMENT c. PRODUCT		N/A	↓ —	-		SEE ATTACHED SHEET			NEW			
13. TITLE OF CHANG			<u> </u>	<u></u>						<u> </u>		
GUNNER'S/CO	MMANDER'S	CONTROL TESTER I	ODIF	ICAT	ION							
14. CONTRACT NO. /	AND LINE ITEM				RING CONTRAC		FFICER					
					st, Middle Initial,	_						
			b. CO	DE		C.	Telephone i					
16. CONFIGURATION M1 SERIES TAN								[7. IN PF	RODUCT S	100 100	
18. ALL LOWER LEV	EL ITEMS AFFE	CTED										
a, NOMENCLATURE GUNNER'S/COI	MMANDER'S	CONTROL TESTER		6. PAR 122	T NO. 33472		c. NSN					
SECOND CHAN 20. NEED FOR CHAN SEE ATTACHEL	IGE: REDIME	TABLE MASTER ARTY INSIONING HARDWAF	RE BF	RACK	ET TO RESO	LVE	FABRICA	TION IS	· - 6	(335) 7		
21. PRODUCTION EF	FECTIVITY BY	SERIAL NUMBER		22. EI	FECT ON PROD	DUCTIO	ON DELIVER	RY SCHE		ميد		
				<u> </u>								
23. RETROFIT 8. RECOMMENDED ITEM EFFECTIVITY					b. SHIP / VEHICLE CLASS AFFECTED							
# VECONIMENDED HEW ELLECHALL												
C. ESTIMATED KIT DELIVERY SCHEDULE				d, LOCATIONS OR SHIP / VEHICLE NUMBERS AFFECTED								
24. ESTIMATED COSTS / SAVINGS UNDER CONTRACT				25. ESTIMATED NET TOTAL COSTS / SAVINGS								
26, SUBMITTING ACT	INITY			b. TIT	LE							
a, AUTHORIZED SIGI 27, APPROVAL / DIS/		ERT A. PIACENTE		T.I.	P.O.							
	HITTOTAL	1										
a. CLASS I APPROVAL RECOMMENDED	DISAPPROV	b. CLASS II AL APPROVED	- 70	ISAPPRO	C. CLASS II	EUR IN C ON OF C	LASSIFI-		NOT CON	ICUR IN CL CHANGE	A\$\$ifi-	
d, GOVERNMENT AC			. SIGN	ATURE				DATE S			DD)	
g. APPROVAL APPROVED DISAPPROVED	n. governmen TA COM , A MSTA	B	. SIGN	ATURE FS	e R. M.	fu s		200	OO C)D)	
1 OF 5												

ECP L9T1007R1 FORM 1692 BLOCK 12 AND 18

DRAWINGS TO BE AFFECTED:

PART NO.	NOMENCLATURE	REV.	NSN NO.	CAGE	NOR
9338670	BRACKET	NEW		19200	1
12283656	PRINTED WIRE BOARD	Ä		19207	2

ECP L9T1007R1
FORM 1692
BLOCK 19 and 20
Recommendation: Accept

ECP L9T1007 had the following descriptions of change:

"ECP L9T1007 has been initiated in order to address various fabrication and manufacturing issues to resolve vendor concerns in making the Gunner's/Commander's Control Tester 12283472. This tester is a Basic Issue Item (BII) for the M1 Series Tank.

First action of this ECP corrects dimensional errors found on the Stable Based Artwork referenced in Printed Wiring Master 12283656. Printed Wiring Master 12283656 is used to create Board, Printed Wiring 12283639, which is found on Circuit Board Assembly 12283638. This circuit board assembly is used in the Gunner's/Commander's Control Tester 12283472, which is the top item that needs correction. The spacing needs to be changed on the Stable Based Artwork to reflect lead spacing from 0.100" to 0.109", otherwise the assembly will not occur. Affected Drawing is only Stable Based Artwork referenced in 12283656.

Second action of this ECP corrects small dimension interference in the housing hardware (a bracket) of the tester assembly. Bracket 9338670 is used on Chassis Assembly 12283600, which is part of the Gunner's/Commander's Control Tester 12283472. Dimension changes are recommended to this bracket to ease assembly of the Chassis Assembly 12283600. Affected drawing is 9338670.

Third action of this ECP is to replace one of the potentiometers used in this tester due to noise issues. In particular, new testers are having a calibration issue where they can not be calibrated due to electrical noise being generated due to "cross-talk" with parallel wires in the wiring harness. A higher Ohmic value potentiometer (250K as opposed to current 100K) has been bench tested in a tester that could not be calibrated with the old potentiometer, and the calibration issue ceased with the new potentiometer installed. Affected drawings are 12283638 and 12283655.

This ECP will encompass all known deficiencies encountered in the last contract for this Gunner's/ Commander's Control Tester 12283472."

The changes occurring in L9T1007R1 consist of removing the potentiometer changes to L9T1007. The rationale of this removal is the following. Upon further testing it has been shown that the current 100K potentiometer can be calibrated in most cases. The cases that do not calibrate, the recommendation of this activity is to utilize the 250K potentiometer in a waiver or deviation mode solution as done on last government contract. Therefore it is not pertinent to include the potentiometer changes in L9T1007, and are dropped from ECP L9T1007.

Therefore the description of changes for L9T1007R1 shall consist of the following:

"ECP L9T1007R1 has been initiated in order to address various fabrication and manufacturing issues to resolve vendor concerns in making the Gunner's/Commander's Control Tester 12283472. This tester is a Basic Issue Item (BII) for the M1 Series Tank.

First action of this ECP corrects dimensional errors found on the Stable Based Artwork referenced in Printed Wiring Master 12283656. Printed Wiring Master 12283656 is used to create Board, Printed Wiring 12283639, which is found on Circuit Board Assembly 12283638. This circuit board assembly is used in the Gunner's/Commander's Control Tester 12283472, which is the top item that needs correction. The spacing needs to be changed on the Stable Based Artwork to reflect lead spacing from 0.100" to 0.109", otherwise the assembly will not occur. Affected Drawing is only Stable Based Artwork referenced in 12283656.

Second action of this ECP corrects small dimension interference in the housing hardware (a bracket) of the tester assembly. Bracket 9338670 is used on Chassis Assembly 12283600, which is part of the Gunner's/Commander's Control Tester 12283472. Dimension changes are recommended to this bracket to ease assembly of the Chassis Assembly 12283600. Affected drawing is 9338670.

							77 20 T T 6	0 0 3 K 1
NOTICE OF REVISION (NOR) THIS REVISION DESCRIBED BELOW HAS BEEN AUTHORIZED FOR THE DOCUMENTS LISTED.							. DATE (YYMMD) 000105	D) Form Approved OMB No. 0704-0188
Aubite reporting burden for this collection of information is estimated to average 2 hours per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the information. Send comments regarding this burden estimate or any other aspect of this collection of information information provided in the control of the collection of information played the collection of information of the collection of information played the collection of information of the collection of information played the collection of information of the collection of the collection of th								
Hojed (0704-0188), Washington, DC 20503 LEASE DO NOT RETURN YOUR COMPLETED FORM TO EITHER OF THESE ADDRESSES, RETURN COMPLETED FORM TO THE GOVERNMENT ISSUING CONTRACTING OFFICER FOR THE CONTRACT / PROCURING ACTIVITY NUMBER LISTED IN ITEM 2 OF THIS FORM.								
4. ORIGINATOR		b. ADDRESS	(Street, City, S	tate. Zio	Code)	5 CAG	E CODE	6. NOR NO.
19200							1	
	BENET LABORATORIES						8. DOCUMENT NO.	
AMSTA-AR-CO	WATERVLIET, NY 12189-4050				67 (6.	19200	9338670	
8. TITLE OF DOCUM	IENI	10. REVISION LE						11. ECP NO.
BRACKET	a. CURRENT NEW					b. NEW	L9T1007R1	
12. CONFIGURATION CHASSIS ASSI	12. CONFIGURATION ITEM (OR SYSTEM) TO WHICH ECP APPLIES CHASSIS ASSEMBLY 12283600, A SUB-PART OF 12283472					NOR SHT 1 OF 2	ECP SHT 3 OF 4	
13, DESCRIPTION O						اــــــا	101-2	3 07 4
	#9338670 SECTION (CHANGE TI	HE FOLLOW	VING:				
SECTION D5	CHANGE DIMENSI	ON EPOM.	# 25n	TO:	".19"			
GEOTION DS	CHANGE DIMENSA	JN FRON;	2PL	10:	2PL			
SECTION C5	CHANGE DIMENSION	ON FROM:	".12"	TO:	<u>".14"</u>			
					•••			
SECTION B6	CHANGE DIMENSION	ON FROM:	"6.08-,04	" TO:	"6.07 - .03"			
SECTION B4	CHANGE DIMENSION	ON FROM:	".50"	TO:	"0.38"			
SECTION C5	CHANGE DIMENSION	NI EDOM.	((ACO .t.AO))	то.	KEAD Soft			
OLOTION CS	CHARGE DIMERSIO	N PROM:	"46° +4°"	10;	"50° -2°"			
								-
								i
	OR GOVERNMENT USE O							
I. (X one) X (1) Existing document supplemented by this NOR may be used in manufacture. (2) Revised document must be received before manufacturer may incorporate this change.								
X (3) Custodian of master document shall make above ravision and furnish revised document.								
O. ACTIVITY AUTHORIZED TO APPROVE CHANGE FOR GOVERNMENT C. TYPED NAME (First, Middle Initial, Last) TACAM, AIMSTA-TR-E TANK VOSE R. MABESA								
I. TITLE	(4	. SIGNATURE						E SIGNED
MECH	EVER	(fose R.	- <i>41</i>]	du -			MMDD) 2000/19
5a. ACTIVITY ACCO	MPLISHING REVISION	. REVISION C	OMPLETED (S	ignature)			E SIGNED
		•	·					MMDD)

L9T100 7 R/ 1. DATE (YYMMDD) 000105 NOTICE OF REVISION (NOR) Form Approved OMB No. 0704-0188 THIS REVISION DESCRIBED BELOW HAS BEEN AUTHORIZED FOR THE DOCUMENTS LISTED. . PROCURING Public reporting burden for this collection of information is estimated to everage 2 hours per response, including the time for reviewing instructions, searching existing dat sources, galhering and maintaining the data needed, and completing and reviewing the information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Department of Defense, Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highwey, Suite 1204, Arington, VA 2202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188), Washington, DC 20503
PLASSE (D. NOT) RETURN YOUR COMPLETED FORM TO EITHER OF THESE ADDRESSES, RETURN COMPLETED FORM TO THE GOVERNMENT ISSUING CONTRACTING OFFICER FOR THE CONTRACT / PROCURING ACTIVITY NUMBER LISTED IN ITEM 2 OF THIS FORM. ACTIVITY NO. L9T1007R1 3 DODAAC 4. ORIGINATOR b. ADDRESS (Street, City, State, Zip Code) 6. CAGE CODE . NOR NO. . TYPED NAME (First, 19200 **US ARMY ARDEC BENET LABORATORIES** BENET LABORATORIES/AMSTA-AR-CCB-EC CAGE CODE 8. DOCUMENT NO. AMSTA-AR-CCB-DD WATERVLIET, NY 12189-4050 19200 C12283656 8. TITLE OF DOCUMENT 10. REVISION LETTER 11. ECP NO. a. CURRENT . NEW **PRINTED WIRING MASTER** L9T1007R1 Α 12. CONFIGURATION ITEM (OR SYSTEM) TO WHICH ECP APPLIES ECP SHT NOR SHT **BOARD, PRINTED WIRING 12283639** 2 OF 2 4 OF 4 13. DESCRIPTION OF REVISION ON PRODUCTION MASTER (STABLE BASED ARTWORK): CHANGE CONNECTOR (PIN) HOLE SPACING FROM: "0.100" INCHES APART TO "0.109" INCHES APART 14. THIS SECTION FOR GOVERNMENT USE ONLY X (1) Existing document supplemented by this NOR may be used in manufacture a. (X one) (2) Revised document must be received before manufacturer may incorporate this change. X (3) Custodian of master document shall make above revision and furnish revised document. b. ACTIVITY AUTHORIZED TO APPROVE CHANGE FOR GOVERNMENT [c, TYPED NAME (First, Middle Initial, Last) TACOM, AMSTA-TR-E/TANK VOSE R. MABESA DATE SIGNED e SIGNATURE Vec R. Makes (YYMMDD) MECH ENGR 2000 0119 15a. ACTIVITY ACCOMPLISHING REVISION b. REVISION COMPLETED (Signature) . DATE SIGNED (YYMMDD)

L9T100 7RI CONFIGURATION CONTROL BOARD DIRECTIVE L9T1007R1 DESIGN ACTIVITY EVALUATION (Check only one) X ECP RFD TRANSFERRED **8**E₽ PROJECT MANAGED RFW OTHER OTHER VECP b. SOLICITATION(s) AFFECTED 3a. CONTRACT(s) AFFECTED N/A N/A 5. COST IMPACT **APPLICATION** RETROFIT BY: Apply to current contracts/solicitations NONE Apply to future applications Attrition Formalizes change previously authorized via: INCREASE Minor Alteration ST MWO DECREASE Associated or Interface Changes as listed in remarks. 6b. MODIFICATION(s) TO SUBMITTED ACTION B. RECOMMENDATION TO CONFIGURATION MANAGER: Ź T QAD X APPROVE NONE AS FOLLOWS: APPROVE WITH MODIFICATION -:- DISAPPROVE OTHER: 9 . POSITION ON RECOMMENDATION TO CONFIGURATION MANAGER IMPACTED CONCUR DOCUMENTS/ TYPED/PRINTED NAME AND SIGNATURE OFFICE SYMBOL TELEPHONE DISCIPLINE YES NO YES NO PRODUCT DRAWINGS Х Х AMSTA-AR-CCB-DD (518) 266-4287 BRYAN J. VAN DE WAL SPECIFICATIONS/ **PACKAGING** DATA SOFTWARE MAINTENANCE OTHER (Specify) VALUE ENGINEERING NOTE: A Notice of Revision (NOR) is required for each document needing revision when a change is recommended for approval. RECOMMEND ACCEPT 9d. DATE 9b. TYPED/PRINTED NAME AND TITLE 9c. SIGNATURE 9a, OFFICE SYMBOL 5 JAN 00 AMSTA-AR-CCB-DD Robert A. Piacente 9e. TELEPHONE TIPO (518) 266-5782